


Pulsed N.M.R.

Super Super Good - 6V Supply - Battery + Reg.

ALL Filaments are on D.C. + Isolated



Transmitter Shielding -

Lo Q Coils

Get Another Rack - Radio Rec. For R.F. Sniffing

Ferrite beads

Shielding or Isolation of ATTENUATOR Circuit

MAYBE use FET Follower CKT or Emitter Follower

TRANSMITTER CKT. - Gnd. Grid GATE Tube is Good (P321)